CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: 18 JAN 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain overcast windy

IDENTIFICATION

PLOT IDENTIFICATION: 113

NAME(S) OF INTERRED:

TOLITAGALOA HEAD

EARLIEST/FIRST BURIAL DATE:

MOST RECENT/LAST BURIAL DATE:

INSCRIPTION:

IN LOVING MEMORY OF

TOLITAGALOA HEAD FRANCIS HEAD

BELOVED WIFE OF LOST AT SEA

THE LATE FRANCIS AUGUST 1920

DIED 3RD SEPT. 1963 AGED 41 YEARS

AGED 76 YEARS "BOTH OF NIUE"

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces illegible/destroyed re-carved

STONECARVER: N/A LOCATION OF MARK: N/A

DESCRIPTION

TYPE OF INTERMENT: individual family undeterminable					
INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker					
ΓΥΡΕ OF PRIMARY STRUCTURE (portion containing inscription):					
concrete slab cemented rock freestacked rock other					
ΓΥΡΕ OF BASE (lowest element supporting primary structure):					
concrete slab cemented rock freestacked rock other					
ΓΥΡΕ OF MARKER (circle all that apply):					
headstone footstone ground tablet basal ruin cross pedestal obelisk					
pedestal column funeral home plaque bedstead					
In inches:					
DIMENSIONS (primary structure) height: 5 width: 36 depth/L: 87					
DIMENSIONS (base) height: 7 width: 46 depth/L: 94.5					
DIMENSIONS (other <u>headstone</u>) height: 2-18 (E-W) width:36 depth/L: 50					
ORIENTATION (direction of inscription): North South East West Unknown					
INTERMENT STATUS: active inactive abandoned					
STATE OF INTERMENT (circle all that apply):					
standing ruin fragment relocated altered replica tilted sunken					
PEDESTAL? yes no BASE? yes no					
ORNAMENT (circle all that apply): none urn sculpture cross plaque					
relief decoration incised decoration metal letter applique ornamental vase					
FURNITURE (circle all that apply): none sculpture container/vase plaque					
immortelles fabric flowers					
LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation					
other					
ENCLOSURE(circle all that apply): curb wall fence none					
GRADE SLOPE: positive negative cross-slope none					
DEGREE OF GRADE: low medium high					

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE				X	
BASALT					
CONCRETE	X	X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
POSITION:	POSITION:
fallen unstable overgrown	reset in ground
tilted marker/ base other	reset to existing base
	resquare botom edge
DETERIORATION:	remove fragments in setting slot
broken cracked losses flaking/sugaring	construct new base
delaminations/detachment	possible new base required
other	stabilize foundation
SOILING:	DETERIORATION:
biological general graffiti efflorescence	structural adhesion repair mortars
painting other	crack fillers flowable grouts
	consolidation
FAILED TREATMENTS:	
metal adhesives/coatings mortar	SOILING:
other	chemical pressure wash
	poultice air abrasion
	FAILED TREATMENTS:
	drill/grind hand tools solvents air abrasion

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Covered in flaking white paint and mildew; headstone edges also painted.

PHOTO:

