

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 18 JAN 2005

WEATHER (circle all that apply):

hot  warm  cool  dry  humid  sunny  rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 114

NAME(S) OF INTERRED: RUSSELL JAMES MORE

EARLIEST/FIRST BURIAL DATE: 9 JULY 1956

MOST RECENT/LAST BURIAL DATE: 9 JULY 1956

INSCRIPTION: IN LOVING MEMORY OF

RUSSELL JAMES MORE

LATE ENGINEERING MECHANIC

FIRST CLASS R.N.Z.N.

HMNZS LACHLAN

DIED 9<sup>TH</sup> JULY 1956

RIP

CONDITION OF INSCRIPTION (circle one): mint  clear but worn

mostly decipherable  traces  illegible/destroyed re-carved

STONECARVER: N/A

LOCATION OF MARK: N/A

SURVEYOR: E. Radewagen

DATE: 18 JAN 2005

PLOT: 114

## DESCRIPTION

TYPE OF INTERMENT:  individual family undeterminable  
INTERMENT REPRESENTATION: tomb/vault  marker/surface slab family marker  
TYPE OF PRIMARY STRUCTURE (portion containing inscription):  
 concrete slab cemented rock freestacked rock other \_\_\_\_\_  
TYPE OF BASE (lowest element supporting primary structure):  
 concrete slab cemented rock freestacked rock other  
TYPE OF MARKER (circle all that apply):  
 headstone footstone ground tablet basal ruin cross pedestal obelisk  
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 8 width: 24 depth/L: 12  
DIMENSIONS (base=primary structure) height: 1 width: 28 depth/L: 78  
DIMENSIONS (other \_\_\_\_\_) height: 25 width: 17.5 depth/L: 9

ORIENTATION (direction of inscription): North South  East West Unknown

INTERMENT STATUS: active  inactive abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted sunken

PEDESTAL?  yes no BASE?  yes no

ORNAMENT (circle all that apply): none urn sculpture cross plaque  
relief decoration  incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply):  none sculpture container/vase plaque

immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete  soil  grass vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb wall fence  none

GRADE SLOPE: positive negative cross-slope  none

DEGREE OF GRADE: low medium high

SURVEYOR: E. Radewagen

DATE: 18 JAN 2005

PLOT: 114

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE	X			X	
BASALT					
CONCRETE		X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable overgrown tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: biological general graffiti efflorescence painting other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

**ongoing deterioration/treatment required 2-5 years**    re-inspect in 5 years

artistic or historic significance

prominent

**monitor**

SUMMARY: Granite pedestal for headstone has been painted white. Entire grave sinking along N edge.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 18 JAN 2005

PLOT: 114