

CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 12 JAN 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain overcast windy

IDENTIFICATION

PLOT IDENTIFICATION: 135

NAME(S) OF INTERRED: SIAOSI KOLI TA'UFO'OU

EARLIEST/FIRST BURIAL DATE: 31 Oct 1983

MOST RECENT/LAST BURIAL DATE: 31 Oct 1983

INSCRIPTION:

In Loving Memory of

SIAOSI KOLI TA'UFO'OU

Fa'ele'i' 27.5.1939 Pekia 31.10.1983

Beloved Husband of FELISITA

Much Loved dad of ROSA & ELUINI

Dearest Grandpa of GEORGE & VIOLET BERIVARD

Always In Our Hearts

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces illegible/destroyed re-carved

STONECARVER: None

LOCATION OF MARK: N/A

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 135

DESCRIPTION

TYPE OF INTERMENT: individual family undeterminable

INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab cemented rock freestacked rock other _____

TYPE OF BASE (lowest element supporting primary structure):

concrete slab cemented rock freestacked rock other _____

TYPE OF MARKER (circle all that apply):

headstone footstone ground tablet basal ruin cross pedestal obelisk
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 2 width: 46 depth/L: 96

DIMENSIONS (base) height: 7 width: 55 depth/L: 104

DIMENSIONS (other plaque furniture) height:4-20 (E-W) width:23 depth/L: 22

ORIENTATION (direction of inscription): North South East West Unknown

INTERMENT STATUS: active inactive abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes no BASE? yes no

ORNAMENT (circle all that apply): none urn sculpture cross plaque

relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): none sculpture container/vase plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation

other _____

ENCLOSURE(circle all that apply): curb wall fence none

GRADE SLOPE: positive negative cross-slope none

DEGREE OF GRADE: low medium high

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 135

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE				X	
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable overgrown tilted marker/ base other <u>stable</u></p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other <u>none</u></p> <p>SOILING: <u>biological</u> general graffiti efflorescence <u>painting</u> other</p> <p>FAILED TREATMENTS: N/A metal adhesives/coatings mortar other <u>none</u></p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical <u>pressure wash</u> poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Plaque base and primary structure base are painted; surface slab unpainted
grave looks as if it is tended to occasionally.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 135