

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 12 JAN 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid    sunny   rain   overcast    windy

## IDENTIFICATION

PLOT IDENTIFICATION: 138

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE: N/A

MOST RECENT/LAST BURIAL DATE: N/A

INSCRIPTION: N/A

CONDITION OF INSCRIPTION (circle one):   mint                      clear but worn

mostly decipherable   traces    illegible/destroyed   re-carved

STONECARVER: N/A

LOCATION OF MARK: N/A

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 138

## DESCRIPTION

TYPE OF INTERMENT: individual family **undeterminable**

INTERMENT REPRESENTATION: tomb/vault **marker/surface slab** family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

**concrete slab** cemented rock freestacked rock other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab cemented rock **freestacked rock** other \_\_\_\_\_

TYPE OF MARKER (circle all that apply): N/A

headstone footstone ground tablet basal ruin cross pedestal obelisk  
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 6 width: 59min. depth/L: 98.5

DIMENSIONS (base) height: 6 width: 30 (from S edge or p.s.)  
depth/L: 128

DIMENSIONS (other \_\_\_\_\_) height: width: depth/L:

ORIENTATION (direction of inscription): North South East West **Unknown**

INTERMENT STATUS: active inactive **abandoned**

STATE OF INTERMENT (circle all that apply):

**standing** ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes **no** BASE? yes **no**

ORNAMENT (circle all that apply): **none** urn sculpture cross plaque  
relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): **none** sculpture container/vase plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete **soil** **grass** vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb wall fence **none**

GRADE SLOPE: positive negative **cross-slope** none

DEGREE OF GRADE: low **medium** high

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 138

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT		X			
CONCRETE	X				
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Slab on freestacked rock base; N edge unknown, highly overgrown as is entire base; one temporary plastic urn on W end of primary structure.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 138