

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: American Samoa Korean Association PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: March 7, 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 160

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE:-----

MOST RECENT/LAST BURIAL DATE:-----

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces  illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK:-----

SURVEYOR: E. Radewagen DATE: 7 Mar 2005 PLOT: 160

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION: tomb/vault  marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply): *missing*

headstone  footstone    ground tablet    basal    ruin    cross    pedestal    obelisk  
pedestal column    funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 4    width: 55    depth/L: 100

DIMENSIONS (base)    height: -    width: -    depth/L: -

DIMENSIONS (vase stand)    height: 14    width: 48    depth/L: 30

ORIENTATION (direction of inscription): North    South    East    West     Unknown

INTERMENT STATUS: active     inactive    abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated     altered    replica    tilted    sunken

PEDESTAL?    yes     no    BASE?    yes     no

ORNAMENT (circle all that apply):  none    urn    sculpture    cross    plaque  
relief decoration    incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply): none     sculpture    container/vase    plaque    immortelles

LANDSCAPE (circle all that apply): brick    asphalt    concrete     soil     grass    vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb    wall    fence     none

GRADE SLOPE: positive    negative    cross-slope     none

DEGREE OF GRADE: low    medium    high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: <b>broken</b>   cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: <b>biological</b>   general graffiti efflorescence <b>painting</b>   other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

SURVEYOR:

E. Radewagen

DATE: 7 Mar 2005

PLOT: 160

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years

artistic or historic significance                      prominent                      monitor

SUMMARY: The entire primary structure is broken in half. Paint, vegetation and mildew need to be removed.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 7 Mar 2005

PLOT: 160