

CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: American Samoa Korean Association PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: March 7, 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain **overcast** windy

IDENTIFICATION

PLOT IDENTIFICATION: 161

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE:-----

MOST RECENT/LAST BURIAL DATE:-----

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces **illegible/destroyed re-carved**

STONECARVER: -----

LOCATION OF MARK:-----

SURVEYOR: E. Radewagen DATE: 7 Mar 2005 PLOT: 161

DESCRIPTION

TYPE OF INTERMENT: individual family undeterminable

INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab cemented rock freestacked rock other _____

TYPE OF BASE (lowest element supporting primary structure):

concrete slab cemented rock freestacked rock other _____

TYPE OF MARKER (circle all that apply): *missing*

headstone footstone ground tablet basal ruin cross pedestal obelisk
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 1 width: 50 depth/L: 100

DIMENSIONS (base) height: 3 width: 58 depth/L: 106

DIMENSIONS (footstone) height: 13 width: 16 depth/L: 3.5

ORIENTATION (direction of inscription): North South East West Unknown

INTERMENT STATUS: active inactive abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes no BASE? yes no

ORNAMENT (circle all that apply): none urn sculpture cross plaque
relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): none sculpture container/vase plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation
other _____

ENCLOSURE(circle all that apply): curb wall fence none

GRADE SLOPE: positive negative cross-slope none

DEGREE OF GRADE: low medium high

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable overgrown tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: biological general graffiti efflorescence painting other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

SURVEYOR:

E. Radewagen

DATE: 7 Mar 2005

PLOT: 161

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance prominent monitor

SUMMARY: The primary structure is cracked with losses. The footstone has been broken in half and top half is fragmented and mostly missing. Paint, vegetation and mildew need to be removed.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 7 Mar 2005

PLOT: 161