

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: American Samoa Korean Association PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: March 7, 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 176

NAME(S) OF INTERRED: Yong Sik Kan

EARLIEST/FIRST BURIAL DATE:-----

MOST RECENT/LAST BURIAL DATE: December 20, 1977

INSCRIPTION:

15-12-1948 ~ 20-12-1977

Yong Sik Kan

(Korean fishing vessel name) #10

CONDITION OF INSCRIPTION (circle one):  mint clear but worn

mostly decipherable  traces  illegible/destroyed  re-carved

STONECARVER: -----

LOCATION OF MARK:-----

SURVEYOR:

E. Radewagen

DATE: 7 Mar 2005

PLOT: 176

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION: tomb/vault  marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone    footstone    ground tablet    basal    ruin    cross    pedestal    obelisk  
pedestal column     funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 4    width: 24    depth/L: 60

DIMENSIONS (base)    height: 10    width: 46    depth/L: 90

DIMENSIONS (plaque base)    height: 11    width: 16    depth/L: 22

ORIENTATION (direction of inscription): North     South    East    West    Unknown

INTERMENT STATUS: active     inactive    abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated     altered    replica    tilted    sunken

PEDESTAL?    yes     no    BASE?     yes    no

ORNAMENT (circle all that apply): none    urn    sculpture    cross     plaque

relief decoration    incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):  none    sculpture    container/vase    plaque    immortelles

LANDSCAPE (circle all that apply): brick    asphalt    concrete     soil     grass    vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb    wall    fence     none

GRADE SLOPE: positive    negative    cross-slope     none

DEGREE OF GRADE: low    medium    high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL				X	
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: biological general graffiti efflorescence painting other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Grave is maintained by the American Samoa Korean Association.

Surrounding vegetation occasionally becomes overgrown. No repairs needed.

PHOTO:

