CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: 24 JAN 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain overcast windy

IDENTIFICATION

PLOT IDENTIFICATION: 17A

NAME(S) OF INTERRED: unknown; attached to Mary Kennison

two infant children acc. to 1927 list

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: ----- possibly same as 17

INSCRIPTION:

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces illegible/destroyed re-carved

STONECARVER: ------ LOCATION OF MARK: -----

DESCRIPTION

family TYPE OFINTERMENT: individual undeterminable INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker TYPE OF PRIMARY STRUCTURE (portion containing inscription): concrete slab cemented rock freestacked rock other rounded concrete casket TYPE OF BASE (lowest element supporting primary structure): concrete slab cemented rock freestacked rock other TYPE OF MARKER (circle all that apply): ----headtstone footstone ground tablet basal ruin cross pedestal obelisk pedestal column funeral home plaque bedstead In inches: height: 6.5 DIMENSIONS (primary structure) width: 46 depth/L: 48 DIMENSIONS (base) height: 8.5 width: 56 depth/L: 56 height: 9.5 DIMENSIONS (other round casket) width: 10.5 depth/L: 31 ORIENTATION (direction of inscription): North South East West Unknown INTERMENT STATUS: active inactive abandoned STATE OF INTERMENT (circle all that apply): standing ruin fragment relocated altered replica tilted sunken no PEDESTAL? BASE? no ves yes ORNAMENT (circle all that apply): none scultpure urn plaque cross relief decoration incised decoration metal letter applique ornamental vase FURNITURE (circle all that apply): none sculpture--caskets container/vase plaque immortelles LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation other ENCLOSURE(circle all that apply): curb wall fence none GRADE SLOPE: positive negative cross-slope none DEGREE OF GRADE: low medium

MATERIALS

| MATERIAL TYPE | PRIMARY STRUCTURE | BASE | SURFACE FINISH | ORNAMENT | ROOF |
|------------------|----------------------|------|-------------------|----------|------|
| MARBLE | 2 | | | | |
| LIMESTONE | | | | | |
| GRANITE | | | | | |
| BASALT | | | | | |
| CONCRETE | X | X | | X | |
| METAL | | | | | |
| STUCCO | | | | | |
| WHITEWASH | | | X | | |
| LIMEWASH | | | | | |
| CEMENTWASH | | | | | |

CONDITIONS

| EXISTING CONDITION | CONSERVATION STRATEGY |
|---|------------------------------------|
| POSITION: | POSITION: |
| fallen unstable overgrown | reset in ground |
| tilted marker/ base other | reset to existing base |
| | resquare botom edge |
| DETERIORATION: | remove fragments in setting slot |
| broken cracked losses flaking/sugaring | construct new base |
| delaminations/detachment | possible new base required |
| other | stabilize foundation |
| | |
| SOILING: | DETERIORATION: |
| biological general graffiti efflorescence | structural adhesion repair mortars |
| painting other | crack fillers flowable grouts |
| | consolidation |
| FAILED TREATMENTS: | |
| metal adhesives/coatings mortar | SOILING: |
| other | chemical pressure wash |
| | poultice air abrasion |
| | |
| | FAILED TREATMENTS: |
| | drill/grind hand tools solvents |
| | air abrasion |

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Grave may mark child birthing death? Two small loaf casket sculptures. Base is shattered on S edge, primary structure covered in cracks and paint W side of p.s. broken NE side as well.

PHOTO:

