CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: American Samoa Korean Association PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: March 7, 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain overcast windy

IDENTIFICATION

PLOT IDENTIFICATION: 180

NAME(S) OF INTERRED: De Son Jyong

EARLIEST/FIRST BURIAL DATE:----

MOST RECENT/LAST BURIAL DATE: September 4, 1978

INSCRIPTION:

 $10-7-1941 \sim 4-9-1978$

De son Jyong

(Korean fishing vessel name) #101

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces illegible/destroyed re-carved

STONECARVER: ------ LOCATION OF MARK:-----

DESCRIPTION

TYPE OFINTERMENT: individual family undeterminable
INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker
TYPE OF PRIMARY STRUCTURE (portion containing inscription):
concrete slab cemented rock freestacked rock other
TYPE OF BASE (lowest element supporting primary structure):
concrete slab cemented rock freestacked rock other
TYPE OF MARKER (circle all that apply):
headstone footstone ground tablet basal ruin cross pedestal obelisk
pedestal column funeral home plaque bedstead
In inches:
DIMENSIONS (primary structure) height: 4 width: 24 depth/L: 60
DIMENSIONS (base) height: 10 width: 46 depth/L: 90
DIMENSIONS (plaque base) height: 11 width: 16 depth/L: 22
ORIENTATION (direction of inscription): North South East West Unknown
INTERMENT STATUS: active inactive abandoned
STATE OF INTERMENT (circle all that apply):
standing ruin fragment relocated altered replica tilted sunken
PEDESTAL? yes no BASE? yes no
ORNAMENT (circle all that apply): none urn sculpture cross plaque
relief decoration incised decoration metal letter applique ornamental vase
FURNITURE (circle all that apply): none sculpture container/vase plaque immortelles
LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation
other
ENCLOSURE(circle all that apply): curb wall fence none
GRADE SLOPE: positive negative cross-slope none
DEGREE OF GRADE: low medium high

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE	STREETER				
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL				X	
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
POSITION:	POSITION:
fallen unstable overgrown	reset in ground
tilted marker/ base other	reset to existing base
	resquare botom edge
DETERIORATION:	remove fragments in setting slot
broken cracked losses flaking/sugaring	construct new base
delaminations/detachment	possible new base required
other	stabilize foundation
SOILING:	DETERIORATION:
biological general graffiti efflorescence	structural adhesion repair mortars
painting other	crack fillers flowable grouts
	consolidation
FAILED TREATMENTS:	
metal adhesives/coatings mortar	SOILING:
other	chemical pressure wash
	poultice air abrasion
	FAILED TREATMENTS:
	drill/grind hand tools solvents
	air abrasion

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP ongoing deterioration/treatment required 2-5 years re-inspect in 5 years artistic or historic significance prominent monitor

SUMMARY: Grave is maintained by the American Samoa Korean Association. Surrounding vegetation occasionally becomes overgrown. No repairs needed.

PHOTO:

