

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 21 JUL 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid   sunny   rain    overcast   windy

## IDENTIFICATION

PLOT IDENTIFICATION: 199

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: -----

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one):   mint                      clear but worn

mostly decipherable   traces    illegible/destroyed   re-carved

STONECARVER:   -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 21 July 2005

PLOT: 199

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION:  tomb/vault    marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock    freestacked rock     other     concrete

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock    freestacked rock     other     concrete

TYPE OF MARKER (circle all that apply):

headstone    footstone    ground tablet    basal    ruin    cross    pedestal    obelisk  
 pedestal column    funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 6    idth: 18    pth/L: 18

DIMENSIONS (base)    height: 6    width: 6    depth/L: 6

DIMENSIONS (other)    height:    width:    depth/L:

ORIENTATION (direction of inscription): North    South    East    West    Unknown

INTERMENT STATUS: active    inactive     abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment     relocated    altered    replica     tilted    sunken

PEDESTAL?     yes    no    BASE?     yes    no

ORNAMENT (circle all that apply): none    urn    sculpture    cross     plaque  
relief decoration    incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):  none    sculpture    container/vase    plaque    immortelles

LANDSCAPE (circle all that apply): brick    asphalt    concrete     soil     grass    vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb    wall     fence    none

GRADE SLOPE: positive    negative     cross-slope    none

DEGREE OF GRADE: low    medium     high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X	X	
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> <b>tilted marker/ base</b> other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other <u>rusting</u></p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: ----- metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: Small concrete marker with possible vase stand. Marker may have been moved from original location. Paint and mildew need to be removed.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 21 July 2005

PLOT: 199