

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 24 JAN 2005

WEATHER (circle all that apply):

hot  warm cool dry  humid sunny rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 21

NAME(S) OF INTERRED: L. DeGrace

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: 1899

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces  illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 21

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION:  tomb/vault    marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock     freestacked rock    other rounded concrete casket

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock     freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone    footstone    ground tablet    basal    ruin    cross    pedestal obelisk  
pedestal column    funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 12    width: 46    depth/L: 87

DIMENSIONS (base) -----    height:    width:    depth/L:

DIMENSIONS (other headstone)    height: 18    width: 42    depth/L: 20

ORIENTATION (direction of inscription):    North    South    East    West     Unknown

INTERMENT STATUS:    active    inactive     abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated    altered    replica    tilted    sunken

PEDESTAL?    yes     no    BASE?    yes     no

ORNAMENT (circle all that apply):     none    urn    sculpture    cross    plaque

relief decoration    incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):     none    sculpture    container/vase    plaque

immortelles

LANDSCAPE (circle all that apply):    brick    asphalt    concrete     soil     grass    vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply):    curb    wall    fence     none

GRADE SLOPE:    positive    negative     cross-slope    none

DEGREE OF GRADE:    low     medium    high

SURVEYOR:    E. Radewagen

DATE: 24 JAN 2005

PLOT: 21

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT	X	X		X	
CONCRETE					
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION:</p> <p>fallen unstable <b>overgrown</b></p> <p>tilted marker/ base other _____</p> <p>DETERIORATION: -----</p> <p>broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING:</p> <p><b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: -----</p> <p>metal adhesives/coatings mortar other _____</p>	<p>POSITION:</p> <p>reset in ground</p> <p>reset to existing base</p> <p>resquare botom edge</p> <p>remove fragments in setting slot</p> <p>construct new base</p> <p>possible new base required</p> <p>stabilize foundation</p> <p>DETERIORATION:</p> <p>structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING:</p> <p>chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS:</p> <p>drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: White paint covers possible headstone on S edge of grave; entire grave is overgrown.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 21