CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery LOCATION: Maoputasi County, Tutuila Island, American Samoa VILLAGE: Satala UTM COORDINATES: 02 533060mE 8421764mN OWNER: CONTACT: PHONE: SURVEYOR: Erika C. Radewagen, M.A. DATE: 21 JAN 2005 WEATHER (circle all that apply): hot warm cool dry humid sunny rain overcast windy **IDENTIFICATION** PLOT IDENTIFICATION: 9 NAME(S) OF INTERRED: WILLIAM P. COLEMAN **BURTON COLEMAN** EARLIEST/FIRST BURIAL DATE: JUNE 1 1921 MOST RECENT/LAST BURIAL DATE: INSCRIPTION: -----CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces illegible/destroyed re-carved

STONECARVER:

SURVEYOR: E. Radewagen DATE: 21 JAN 2005 PLOT: 9

LOCATION OF MARK: -----

DESCRIPTION

TYPE OFINTERMENT: individual family undeterminable
INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker
TYPE OF PRIMARY STRUCTURE (portion containing inscription):
concrete slab cemented rock freestacked rock other
TYPE OF BASE (lowest element supporting primary structure):
concrete slab cemented rock freestacked rock other
TYPE OF MARKER (circle all that apply):
headtstone footstone ground tablet basal ruin cross pedestal obelisk
pedestal column funeral home plaque bedstead
In inches:
DIMENSIONS (primary structure) height: 6 width: 31 depth/L: 79
DIMENSIONS (base) height: 0 width: 31 depth/L: 79
DIMENSIONS (other obelisk posts) height: 34 width: 8 depth/L: 8
ORIENTATION (direction of inscription): North South East West Unknown
INTERMENT STATUS: active inactive abandoned
STATE OF INTERMENT (circle all that apply):
standing ruin fragment relocated altered replica tilted sunken
PEDESTAL? yes no BASE? yes no
ORNAMENT (circle all that apply): none urn scultpure cross plaque
relief decoration incised decoration metal letter applique ornamental vase
FURNITURE (circle all that apply): none sculpture container/vase plaque immortelles
LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation
other
ENCLOSURE(circle all that apply): curb wall fence none
GRADE SLOPE: positive negative cross-slope none
DEGREE OF GRADE: low medium high

SURVEYOR: E. Radewagen DATE: 21 JAN 2005 PLOT: 9

MATERIALS

MATERIAL	PRIMARY	BASE	SURFACE	ORNAMENT	ROOF
TYPE	STRUCTURE		FINISH		
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL				X	
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

_	
EXISTING CONDITION	CONSERVATION STRATEGY
POSITION:	POSITION:
fallen unstable overgrown	reset in ground
tilted marker/ base other	reset to existing base
	resquare botom edge
DETERIORATION:	remove fragments in setting slot
broken cracked losses flaking/sugaring	construct new base
delaminations/detachment	possible new base required
other	stabilize foundation
SOILING:	DETERIORATION:
biological general graffiti efflorescence	structural adhesion repair mortars
painting other	crack fillers flowable grouts
	consolidation
FAILED TREATMENTS:	
metal adhesives/coatings mortar	SOILING:
other	chemical pressure wash
	poultice air abrasion
	FAILED TREATMENTS:
	drill/grind hand tools solvents
	air abrasion

SURVEYOR: E. Radewagen DATE: 21 JAN 2005 PLOT: 9

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance prominent monitor

SUMMARY: Concrete slab and three standing obelisk posts; missing chains, fallen obelisk visible; thick white paint and mildew on entire tomb; tilting/sinking down-slope S side.

PHOTO:



SURVEYOR: E. Radewagen DATE: 21 JAN 2005 PLOT: 9