

CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: American Samoa Korean Association PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: July 21, 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain **overcast** windy

IDENTIFICATION

PLOT IDENTIFICATION: FEATURE 1

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE:-----

MOST RECENT/LAST BURIAL DATE:-----

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces **illegible/destroyed re-carved**

STONECARVER: -----

LOCATION OF MARK:-----

SURVEYOR: E. Radewagen DATE: 21 July 2005 PLOT: Fe. 1

DESCRIPTION

TYPE OF INTERMENT: individual family **undeterminable**

INTERMENT REPRESENTATION: **tomb/vault** marker/surface slab family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab cemented rock freestacked rock other _____

TYPE OF BASE (lowest element supporting primary structure):

concrete slab **cemented rock** freestacked rock other _____

TYPE OF MARKER (circle all that apply): N/A

headstone footstone ground tablet basal ruin cross pedestal obelisk
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 4-40 width: 65 depth/L: 80

DIMENSIONS (base) height: - width: - depth/L: -

DIMENSIONS (other) height: - width: - depth/L: -

ORIENTATION (direction of inscription): North South East West **Unknown**

INTERMENT STATUS: active **inactive** abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted **sunken**

PEDESTAL? yes **no** BASE? yes **no**

ORNAMENT (circle all that apply): **none** urn sculpture cross plaque
relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): **none** sculpture container/vase plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete **soil grass** vegetation
other _____

ENCLOSURE(circle all that apply): curb wall fence **none**

GRADE SLOPE: positive negative **cross-slope** none

DEGREE OF GRADE: low medium **high**

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT		X			
CONCRETE	X	X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable overgrown tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: biological general graffiti efflorescence painting other</p> <p>FAILED TREATMENTS: metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

SURVEYOR:

E. Radewagen

DATE: 21 July 2005

PLOT: Fe. 1

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: The primary structure has large cracks and broken . The grave marker does not belong to the feature. It is unlikely that this is a grave. The south side is eroding
Paint, vegetation and mildew need to be removed.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 21 July 2005

PLOT: Fe. 1