CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: 24 JAN 2005

WEATHER (circle all that apply):

hot warm cool dry humid sunny rain overcast windy

IDENTIFICATION

PLOT IDENTIFICATION: 60

NAME(S) OF INTERRED: Son of M. Sutherland

EARLIEST/FIRST BURIAL DATE: -------

MOST RECENT/LAST BURIAL DATE: JULY 3 1935

INSCRIPTION: BABY SUTHERLAND
JULY 3 - 1935

CONDITION OF INSCRIPTION (circle one): mint clear but worn
mostly decipherable traces illegible/destroyed re-carved

STONECARVER: --------- LOCATION OF MARK: ----------

SURVEYOR: E. Radewagen DATE: 24 JAN 2005 PLOT: 60

DESCRIPTION

TYPE OFINTERMENT: individual family undeterminable

INTERMENT REPRESENTATION: tomb/vault marker/surface slab family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab cemented rock freestacked rock other _____

TYPE OF BASE (lowest element supporting primary structure):

concrete slab cemented rock freestacked rock other _____

TYPE OF MARKER (circle all that apply): --------

headtstone footstone ground tablet basal ruin cross pedestal obelisk

pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 14 width: 16 depth/L: 34.5

DIMENSIONS (base) buried height: width: depth/L:

DIMENSIONS (other _____) height: width: depth/L:

ORIENTATION (direction of inscription): North South East West Unknown

INTERMENT STATUS: active inactive abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes no BASE? yes no

ORNAMENT (circle all that apply): none urn scultpure cross plaque

relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): none sculpture container/vase plaque

immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete soil grass vegetation

other_____

ENCLOSURE(circle all that apply): curb wall fence none

GRADE SLOPE: positive negative cross-slope none

DEGREE OF GRADE: low medium high

SURVEYOR: E. Radewagen DATE: 24 JAN 2005 PLOT: 60

MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL				X	
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
POSITION:	POSITION:
fallen unstable overgrown	reset in ground
tilted marker/ base other partially buried	reset to existing base
	resquare botom edge
DETERIORATION:	remove fragments in setting slot
broken cracked losses flaking/sugaring	construct new base
delaminations/detachment	possible new base required
other _____	stabilize foundation
SOILING:	DETERIORATION:
biological general graffiti efflorescence	structural adhesion repair mortars
painting other	crack fillers flowable grouts
	consolidation
FAILED TREATMENTS: --------	
metal adhesives/coatings mortar	SOILING:
other _____	chemical pressure wash
	poultice air abrasion
	FAILED TREATMENTS:
	drill/grind hand tools solvents
	air abrasion

SURVEYOR: E. Radewagen DATE: 24 JAN 2005 PLOT: 60

COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance prominent monitor

SUMMARY: Partially buried from flood 2003. Sunken towards SE corner. Thick white paint and mildew need to be removed. Rounded casket primary structure sculpture.

PHOTO:

SURVEYOR: E. Radewagen DATE: 24 JAN 2005 PLOT: 60