

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 12 JAN 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid   sunny   rain    overcast    windy

## IDENTIFICATION

PLOT IDENTIFICATION: 130

NAME(S) OF INTERRED: -----

EARLIEST/FIRST BURIAL DATE: N/A

MOST RECENT/LAST BURIAL DATE: N/A

INSCRIPTION: N/A

CONDITION OF INSCRIPTION (circle one):   mint                      clear but worn

mostly decipherable   traces    illegible/destroyed   re-carved

STONECARVER: N/A

LOCATION OF MARK: N/A

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 130

## DESCRIPTION

TYPE OF INTERMENT: individual family **undeterminable**

INTERMENT REPRESENTATION: tomb/vault **marker/surface slab** family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

**concrete slab** cemented rock freestacked rock other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab **cemented rock** freestacked rock other \_\_\_\_\_

TYPE OF MARKER (circle all that apply): N/A

headstone footstone ground tablet basal ruin cross pedestal obelisk  
pedestal column funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 5.5 width: 46 depth/L: 106

DIMENSIONS (base) height: 1.5 width: 87 depth/L: 134

DIMENSIONS (other \_\_\_\_\_) height: width: depth/L:

ORIENTATION (direction of inscription): North South East West **Unknown**-no  
inscription

INTERMENT STATUS: active inactive **abandoned**

STATE OF INTERMENT (circle all that apply):

**standing** ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes **no** BASE? yes **no**

ORNAMENT (circle all that apply): **none** urn sculpture cross plaque  
relief decoration incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): **none** sculpture container/vase plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete soil **grass** vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb wall fence **none**

GRADE SLOPE: positive negative **cross-slope** none

DEGREE OF GRADE: **low** medium high

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 130

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT		X			
CONCRETE	X	X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: N/A broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: N/A metal adhesives/coatings mortar other _____</p>	<p>POSITION: N/A reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: N/A structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical <b>pressure wash</b> poultice air abrasion</p> <p>FAILED TREATMENTS: N/A drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    **re-inspect in 5 years**

artistic or historic significance

prominent

**monitor**

SUMMARY: Stable interment made of concrete; only visible concern is flaking white paint on primary structure; no inscription/marker to indicate burial date or person.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 130