

## CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT: Masonic Lodge of American Samoa PHONE:

SURVEYOR: Erika C. Radewagen, M.A. DATE: 12 JAN 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid   sunny   rain    overcast    windy

### IDENTIFICATION

PLOT IDENTIFICATION: 132

NAME(S) OF INTERRED: LAWRENCE R. MORAN

EARLIEST/FIRST BURIAL DATE: 1984

MOST RECENT/LAST BURIAL DATE: 1984

INSCRIPTION:

In Loving Memory

LAWRENCE R. MORAN

1892 - 1984

CONDITION OF INSCRIPTION (circle one):  mint   clear but worn

mostly decipherable    traces    illegible/destroyed re-carved

STONECARVER: NONE

LOCATION OF MARK:

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 132

## DESCRIPTION

TYPE OF INTERMENT:  individual family undeterminable

INTERMENT REPRESENTATION: tomb/vault  marker/surface slab family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab cemented rock freestacked rock other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab  cemented rock freestacked rock other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone footstone ground tablet basal ruin cross pedestal obelisk  
pedestal column  funeral home plaque bedstead

In inches:

DIMENSIONS (primary structure) height: 4 width: 47.5 depth/L: 94

DIMENSIONS (base) height: 3 width: 53 depth/L: 101

DIMENSIONS (other plaque) height: 2-3.5 width: 24.5 depth/L: 13

ORIENTATION (direction of inscription): North South East  West Unknown

INTERMENT STATUS:  active inactive abandoned

STATE OF INTERMENT (circle all that apply):

standing ruin fragment relocated altered replica tilted sunken

PEDESTAL? yes  no BASE? yes  no

ORNAMENT (circle all that apply): none urn sculpture cross  plaque

relief decoration  incised decoration metal letter applique ornamental vase

FURNITURE (circle all that apply): none sculpture container/vase  plaque immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete  soil  grass vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb wall fence  none

GRADE SLOPE: positive negative  cross-slope none

DEGREE OF GRADE:  low medium high

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 132

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE				X	
LIMESTONE					
GRANITE					
BASALT		X			
CONCRETE	X	X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

### CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: N/A metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: <b>chemical</b> <b>pressure wash</b> poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 132

# COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    **re-inspect in 5 years**

artistic or historic significance

prominent

**monitor**

SUMMARY: N and E edges of plot completely overgrown. Cannot find base outline. Interment is stable; only concern white paint on primary structure. 3 Masonic Order symbols by inscription : 2 headed eagle; saber with circled star and figurehead; square compass with G.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 12 JAN 2005

PLOT: 132