

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 24 JAN 2005

WEATHER (circle all that apply):

hot  warm cool dry  humid sunny rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 26

NAME(S) OF INTERRED: J. Cox POWERS

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: -----

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable traces  illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 26

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION: tomb/vault  marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock     freestacked rock    other rounded concrete casket

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock     freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply): N/A

headstone    footstone    ground tablet    basal    ruin    cross    pedestal    obelisk  
pedestal column    funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 13    width: 41    depth/L: 80

DIMENSIONS (base ) -----    height:    width:    depth/L:

DIMENSIONS (other -----)    height:    width:    depth/L:

ORIENTATION (direction of inscription): North    South    East    West     Unknown

INTERMENT STATUS: active    inactive     abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated    altered    replica    tilted     sunken

PEDESTAL?    yes     no    BASE?    yes     no

ORNAMENT (circle all that apply):  none    urn    sculpture    cross    plaque  
relief decoration    incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):  none    sculpture    container/vase    plaque

immortelles

LANDSCAPE (circle all that apply): brick    asphalt    concrete     soil     grass    vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb    wall    fence     none

GRADE SLOPE: positive    negative     cross-slope    none

DEGREE OF GRADE: low     medium    high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT	X	X			
CONCRETE					
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION:</p> <p>fallen <b>unstable</b> <b>overgrown</b></p> <p>tilted marker/ base other _____</p> <p>DETERIORATION: -----</p> <p>broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING:</p> <p><b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: -----</p> <p>metal adhesives/coatings mortar other _____</p>	<p>POSITION:</p> <p>reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION:</p> <p>structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING:</p> <p>chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS:</p> <p>drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action **unstable deterioration/ASAP**

ongoing deterioration/treatment required 2-5 years re-inspect in 5 years

artistic or historic significance

prominent

monitor

SUMMARY: S edge of rock mound is intact; N half is buried. Coconut tree located just off E edge; rocks are overgrown and painted white.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 26