

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 24 JAN 2005

WEATHER (circle all that apply):

hot  warm  cool  dry  humid  sunny  rain  overcast  windy

## IDENTIFICATION

PLOT IDENTIFICATION: 39

NAME(S) OF INTERRED: Mr. William Hill Yandall

Mrs W H Yandall (Palolo)

EARLIEST/FIRST BURIAL DATE: DEC 12 1903 {remains moved to cemetery

MOST RECENT/LAST BURIAL DATE: MAY 9 1910 Apr 1 1925

INSCRIPTION: Mr WILLIAM HILL YANDALL

DIED MAY 9 1910

AND

MRS. W H YANDALL

PALOLO

DIED DEC 12 1903

CONDITION OF INSCRIPTION (circle one): mint clear but worn

mostly decipherable  traces  illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 39

## DESCRIPTION

TYPE OF INTERMENT: individual  family  undeterminable

INTERMENT REPRESENTATION:  tomb/vault  marker/surface slab  family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab  cemented rock  freestacked rock  other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab  cemented rock  freestacked rock  other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone  footstone  ground tablet  basal  ruin  cross  pedestal obelisk  
 pedestal column  funeral home plaque  bedstead

In inches:

DIMENSIONS (primary structure) height: 18.5 width: 53.5 depth/L: 78

DIMENSIONS (base) height: 17 width: 85 depth/L: 100

DIMENSIONS (other \_\_\_\_\_) height: width: depth/L:

ORIENTATION (direction of inscription): North South  East  West  Unknown

INTERMENT STATUS: active inactive  abandoned

STATE OF INTERMENT (circle all that apply):

standing  ruin  fragment  relocated  altered  replica  tilted  sunken

PEDESTAL? yes  no BASE? yes  no

ORNAMENT (circle all that apply): none  urn  sculpture  cross  plaque

relief decoration  incised decoration  metal letter applique  ornamental vase

FURNITURE (circle all that apply):  none  sculpture  container/vase  plaque

immortelles

LANDSCAPE (circle all that apply): brick asphalt concrete  soil  grass  vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb wall fence  none

GRADE SLOPE: positive negative  cross-slope  none

DEGREE OF GRADE: low medium  high

SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 39

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT		X			
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen <b>unstable</b> overgrown <b>tilted marker/ base</b> other _____</p> <p>DETERIORATION: <b>broken</b> <b>cracked</b> <b>losses</b> <b>flaking/sugaring</b> delaminations/detachment other _____</p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: ----- metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

**hazardous/immediate action**    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    re-inspect in 5 years


artistic or historic significance

prominent

monitor

SUMMARY: Cover of vault cracked throughout, broken on west side. Not stable headstone broken, fragments are visible as is metal reinforcements. Sugaring and flaking in exposed concrete areas; thick white paint flaking across entire primary structure.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 24 JAN 2005

PLOT: 39