

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 27 JAN 2005

WEATHER (circle all that apply):

hot    warm    cool    dry     humid     sunny    rain    overcast    windy

## IDENTIFICATION

PLOT IDENTIFICATION: 46

NAME(S) OF INTERRED: R. M. WALKER

LESINA WELLS WALKER

EARLIEST/FIRST BURIAL DATE: MAR 22 1927 {daughter says 2<sup>nd</sup> grave is mother}

MOST RECENT/LAST BURIAL DATE: SEPT 12 1927

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one):    mint                    clear but worn

mostly decipherable    traces     illegible/destroyed    re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 27 JAN 2005

PLOT: 46

## DESCRIPTION

TYPE OF INTERMENT: individual  family  undeterminable

INTERMENT REPRESENTATION:  tomb/vault  marker/surface slab  family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab  cemented rock  freestacked rock  other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab  cemented rock  freestacked rock  other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone  footstone  ground tablet  basal  ruin  cross  pedestal obelisk  
pedestal column  funeral home plaque  bedstead

In inches:

DIMENSIONS (primary structure)      height: 8      width: 32.5      depth/L: 73

DIMENSIONS (base)                      height: 7.5      width: 97      depth/L: 89

DIMENSIONS (other \_\_\_\_\_)      height: 40      width: 25.5      depth/L: 4

ORIENTATION (direction of inscription): North  South  East  West  Unknown

INTERMENT STATUS: active  inactive  abandoned

STATE OF INTERMENT (circle all that apply):

standing  ruin  fragment  relocated  altered  replica  tilted  sunken

PEDESTAL?                      yes  no                       BASE?                      yes  no

ORNAMENT (circle all that apply): none  urn  sculpture  cross  plaque

relief decoration  incised decoration  metal letter applique  ornamental vase

FURNITURE (circle all that apply):  none  sculpture  container/vase  plaque  immortelles

LANDSCAPE (circle all that apply): brick  asphalt  concrete  soil  grass  vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply):  curb  wall  fence  none  cemented rock

GRADE SLOPE: positive  negative  cross-slope  none

DEGREE OF GRADE: low   medium  high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT					
CONCRETE	X	X		X	
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p>POSITION: fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p>DETERIORATION: ----- broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p>SOILING: <b>biological</b> general graffiti efflorescence <b>painting</b> other</p> <p>FAILED TREATMENTS: ----- metal adhesives/coatings mortar other _____</p>	<p>POSITION: reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p>DETERIORATION: structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p>SOILING: chemical pressure wash poultice air abrasion</p> <p>FAILED TREATMENTS: drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    **re-inspect in 5 years**

artistic or historic significance

prominent

**monitor**

SUMMARY: Double grave with two crosses and open box concrete primary structure filled with basalt cobbles. Overgrown, covered in mildew and white paint.

PHOTO:



SURVEYOR: E. Radewagen

DATE: 27 JAN 2005

PLOT: 46