

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 27 JAN 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid   sunny   rain    overcast   windy

## IDENTIFICATION

PLOT IDENTIFICATION: 72

NAME(S) OF INTERRED: UTUONE LAVATA`I

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: AUG 18 1942

INSCRIPTION: -----

CONDITION OF INSCRIPTION (circle one):   mint    clear but worn

mostly decipherable   traces   illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: E. Radewagen

DATE: 27 JAN 2005

PLOT: 72

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION: tomb/vault  marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription): Only one rock visible,  
grave covered by plumeric trunk and other vegetation.

concrete slab     cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock     freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone    footstone    ground tablet    basal    ruin    cross    pedestal obelisk  
pedestal column    funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 4    width: 44    depth/L: 29

DIMENSIONS (base) ---    height: 17    width: 55    depth/L: 79

DIMENSIONS (other \_\_\_\_\_)    height: 25    width: 13    depth/L: 4

ORIENTATION (direction of inscription): North    South     East    West    Unknown

INTERMENT STATUS: active     inactive    abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated    altered    replica    tilted    sunken

PEDESTAL?    yes     no    BASE?    yes     no

ORNAMENT (circle all that apply):  none    urn    sculpture    cross    plaque  
relief decoration     incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):  none    sculpture    container/vase    plaque    immortelles

LANDSCAPE (circle all that apply): brick    asphalt    concrete     soil     grass    vegetation  
other \_\_\_\_\_

ENCLOSURE(circle all that apply): curb    wall    fence     none

GRADE SLOPE: positive    negative    cross-slope     none

DEGREE OF GRADE: low    medium    high

SURVEYOR: E. Radewagen

DATE: 27 JAN 2005

PLOT: 72

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE					
BASALT	X	X		X	
CONCRETE	X				
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
<b>CORAL</b>		X			

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p><b>POSITION:</b> fallen unstable <b>overgrown</b> tilted marker/ base other _____</p> <p><b>DETERIORATION:</b> broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p><b>SOILING:</b> biological general graffiti efflorescence <b>painting</b> other</p> <p><b>FAILED TREATMENTS: --</b> metal adhesives/coatings mortar other _____</p>	<p><b>POSITION:</b> reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p><b>DETERIORATION:</b> structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p><b>SOILING:</b> chemical pressure wash poultice air abrasion</p> <p><b>FAILED TREATMENTS:</b> drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    **re-inspect in 5 years**

artistic or historic significance

prominent

monitor

### SUMMARY:

Grave looks recently tended; headstone sits on concrete slab that looks repaired w/ cemented rocks; E ½ of grave consists of rock outline filled with coral gravel. Paint should be cleaned up.

### PHOTO:



SURVEYOR: E. Radewagen

DATE: 27 JAN 2005

PLOT: 72