

# CEMETERY SURVEY FORM

SITE NAME: Satala Naval Cemetery (AS-25-055)

LOCATION: Maoputasi County, Tutuila Island, American Samoa

VILLAGE: Satala

UTM COORDINATES: 02 533060mE 8421764mN

OWNER:

CONTACT:

PHONE:

SURVEYOR: Erika C. Radewagen, M.A.

DATE: 20 January 2005

WEATHER (circle all that apply):

hot   warm   cool   dry    humid   sunny   rain    overcast   windy

## IDENTIFICATION

PLOT IDENTIFICATION: 94

NAME(S) OF INTERRED: Victor Peter Chanel

EARLIEST/FIRST BURIAL DATE: -----

MOST RECENT/LAST BURIAL DATE: January 19 1990

INSCRIPTION: Victor Peter Chanel

May 21 1944 – Jan 19 1990

In Loving Memory

Of Our Beloved Dad

And Grandpa

CONDITION OF INSCRIPTION (circle one):   mint    clear but worn

mostly decipherable   traces   illegible/destroyed re-carved

STONECARVER: -----

LOCATION OF MARK: -----

SURVEYOR: ECR

DATE: 20 Jan 2005

PLOT: 94

## DESCRIPTION

TYPE OF INTERMENT:  individual    family    undeterminable

INTERMENT REPRESENTATION:  tomb/vault    marker/surface slab    family marker

TYPE OF PRIMARY STRUCTURE (portion containing inscription):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF BASE (lowest element supporting primary structure):

concrete slab    cemented rock    freestacked rock    other \_\_\_\_\_

TYPE OF MARKER (circle all that apply):

headstone    footstone    ground tablet    basal    ruin    cross    pedestal obelisk  
pedestal column     funeral home plaque    bedstead

In inches:

DIMENSIONS (primary structure)    height: 7    width: 5    depth/L: 104

DIMENSIONS (base)    height: 7    width: 5    depth/L: 104

DIMENSIONS (other)    height: -    width:-    depth/L: -

ORIENTATION (direction of inscription):    North    South     East    West    Unknown

INTERMENT STATUS:  active    inactive    abandoned

STATE OF INTERMENT (circle all that apply):

standing    ruin    fragment    relocated    altered    replica    tilted    sunken

PEDESTAL?    yes     no    BASE?    yes     no

ORNAMENT (circle all that apply):    none    urn    sculpture     cross     plaque

relief decoration     incised decoration    metal letter applique    ornamental vase

FURNITURE (circle all that apply):    none    sculpture    container/vase    plaque     immortelles

LANDSCAPE (circle all that apply):    brick    asphalt    concrete     soil     grass    vegetation

other \_\_\_\_\_

ENCLOSURE(circle all that apply):    curb    wall    fence     none

GRADE SLOPE:    positive    negative    cross-slope     none

DEGREE OF GRADE:    low    medium    high

## MATERIALS

MATERIAL TYPE	PRIMARY STRUCTURE	BASE	SURFACE FINISH	ORNAMENT	ROOF
MARBLE					
LIMESTONE					
GRANITE				X	
BASALT					
CONCRETE	X	X			
METAL					
STUCCO					
WHITEWASH			X		
LIMEWASH					
CEMENTWASH					

## CONDITIONS

EXISTING CONDITION	CONSERVATION STRATEGY
<p><b>POSITION:</b> fallen unstable overgrown tilted marker/ base other _____</p> <p><b>DETERIORATION:</b> broken cracked losses flaking/sugaring delaminations/detachment other _____</p> <p><b>SOILING:</b> biological general graffiti efflorescence painting other</p> <p><b>FAILED TREATMENTS:</b> metal adhesives/coatings mortar other _____</p>	<p><b>POSITION:</b> reset in ground reset to existing base resquare botom edge remove fragments in setting slot construct new base possible new base required stabilize foundation</p> <p><b>DETERIORATION:</b> structural adhesion repair mortars crack fillers flowable grouts consolidation</p> <p><b>SOILING:</b> chemical pressure wash poultice air abrasion</p> <p><b>FAILED TREATMENTS:</b> drill/grind hand tools solvents air abrasion</p>

## COMMENTS

CONSERVATION PRIORITY (circle all that apply):

hazardous/immediate action    unstable deterioration/ASAP

ongoing deterioration/treatment required 2-5 years    **re-inspect in 5 years**

artistic or historic significance

prominent

monitor

SUMMARY: The concrete slab is covered in layers of thick white paint and the painted surface has mildew patches. There is some paint on the inscribed plaque. Mildew should be washed off and painted should be removed.

PHOTO:



SURVEYOR: ECR

DATE: 20 Jan 2005

PLOT: 94